Bury Lane Playing Field. Summary of recommendations in RoSPA Annual Inspection Report.

Mats. Silted up and compacted. Lift and relay. 2x3

Algae growth on equipment. Clean and treat. 2x3

Info signs + emergency contact at each entrance. 2x2

Picnic Table. Area around table eroded, potentially slippery. Reinstate eroded area. 2x4

Litter bin. Satisfactory. No recommendations.

Play Panel. Slightly loose in foundations. Monitor & reset if required. 2x3

Double swing. Gaps between mats – trip hazard. Re-secure grass mat tiles. 2x4

Trim Trail.

a) timber elements have number of splits - may affect the stability of the item or allow water ingress which will accelerate the rotting process. Monitor to ensure the splits do not cross through fixing points of the structure and / or cause any instability. 2x3
b) connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains. Monitor use and replace with compliant chains during next maintenance cycle. 2x3
c) Loose fittings. Secure all loose fittings. 2x3

Basket swing. The chain openings are in excess of the maximum of 8.6mm recommended by BS EN 1176. Monitor use and replace with compliant chains during next maintenance cycle. 1x5

Zip wire. We recommend that the main cable and fixing security is inspected at least in accordance with the manufacturers recommendations to check for wear, damage, security or internal rusting of the cable and associated components. 2x4 COMPLETED.
Zip wire seat. Risk assessment not undertaken. 0x0

Multiplay slide.

a) The surfacing dimensions are short and do not meet with the requirements of the current applicable standard (the shortfall is 56mm adjacent to the slide entry). Monitor - no remedial action recommended. 2x3
b) Soil has migrated onto the safety surface. Remove the soil. 2x4
c) There is weed / vegetation growth on or around the surfacing. Remove weeds/vegetation. 2x3

1x5 Likelihood Low. Possible Severity Low risk – Monitor.
2x2 Likelihood Low. Possible Severity Low/Medium – carry out recommendations.
2x3 Likelihood Low. Possible Severity Low/Medium – carry out recommendations.
2x4 Likelihood Low. Possible Severity Low/Medium – carry out recommendations.

The risk assessment is based on a likelihood x possible severity of injury index with one being the lowest and safest value and five being the highest and most severe value.

Risk Score	Risk Categories
1 - 5	Low risk - Monitor
6 - 10	Low/medium risk - Carry out the inspectors recommendations
12 - 15	Medium risk - Programme actions to remove the hazard
15 - 16	Medium/high risk - Take action at the earliest possible opportunity / isolate the equipment
20 - 25	Unacceptable risk - Take immediate action to reduce the risk.

8 September 2026. clerk@wigmoregroupparishcouncil.gov.uk